





	F,S	F,S	F,S	F,S	F,S			F,S		F,S	S	F,S
SIZE CODE	HXB	SKT	BCS	FCS	FW			LW		HXN		AXN
					N	R	W	R	X	STD HXN	JAM JXN	
0000 = A												
000 = B												
00 = C												
0 = D		X	X	X	X	X	X			X		
1 = E		X	X	X	X	X	X			X		
2 = F		X	X	X	X	X	X	X	X	X		
3 = G		X	X	X	X	X	X	X	X	X		
4 = H		X	X	X	X	X	X	X	X	X		
5 = I		X	X	X	X	X	X	X	X	X		
6 = J		X	X	X	X	X	X	X	X	X		X
8 = K		X	X	X	X	X	X	X	X	X		X
10 = L		X	X	X	X	X	X	X	X	X		X
12 = M		X			X	X	X	X	X	X		X
1/4 = N	X	X	X	X	X	X	X	X	X	X	X	X
5/16 = O	X	X	X	X	X	X	X	X	X	X	X	X
3/8 = P	X	X	X	X	X	X	X	X	X	X	X	X
7/16 = Q	X	X	X	X	X	X	X	X	X	X	X	X
1/2 = R	X	X	X	X	X	X	X	X	X	X	X	X
9/16 = S	X	X			X	X	X	X	X	X	X	X
5/8 = T	X	X	X	X	X	X	X	X	X	X	X	X
3/4 = U	X	X		X	X	X	X	X	X	X	X	X
7/8 = V	X	X			X	X	X	X	X	X	X	X
1.000 = W	X	X			X	X	X	X	X	X	X	X
1-1/8 = X	X	X			X	X	X	X	X	X	X	X
1-1/4 = Y	X	X			X	X	X	X	X	X	X	X
1-3/8 = Z1	X	X			X	X	X	X	X	X	X	
1-1/2 = Z2	X	X			X	X	X	X	X	X	X	
1-3/4 = Z3	X	X			X	X	X			X	X	
2.000 = Z4	X	X			X	X	X			X	X	

X = INDICATES ITEMS IN THE LIBRARY

PRODUCT #1200

MECH-LIB3 - INDEX PAGE 3 OF 3